

Assessment Impact by Assessment Methods
 Seward County Community College/Area Tech School
 Program - Autobody Collision Repair

Direct

Program - Autobody Collision Repair

Live work, I-Car Tests:

WKR01,FCR01,DAM01,DAM02,TRM01,STS01,EXT01,GLA01,WNW01,PLA01,PLA02,ADH01,WCS01,WCS04,EXT02,WCS02,WCS03,MEA01,SSS01,CPS01,FOM01,SPS01,SPS02,SPS03.SPS04,SPS05,SPS06,REF04,REF01,REF02,REF03,DAM03,PWR01

Outcome: Analyze structural damage - Analyze automotive structural damage and repair requirements

Benchmark: 90%

Results			
Result	Action	Follow-Up	Action Status
05/23/2014 - 3 of 4 students passed with a 90% or above . benchmark not meet at 75%			Action Plan in Progress
Result Type: Benchmark Not Met			

Live work, I-Car Tests:

WKR01,FCR01,DAM01,DAM02,TRM01,STS01,EXT01,GLA01,WNW01,PLA01,PLA02,ADH01,WCS01,WCS04,EXT02,WCS02,WCS03,MEA01,SSS01,CPS01,FOM01,SPS01,SPS02,SPS03.SPS04,SPS05,SPS06,REF04,REF01,REF02,REF03,DAM03,PWR01

Outcome: Non-structural damage - Analyze automotive non-structural damage and repair requirements

Benchmark: 90%

Results			
Result	Action	Follow-Up	Action Status
05/23/2014 - 19 of 21 completed their competencies with a 85% or above. benchmark is meet at 90%			No Action Required
Result Type: Benchmark Met			

Live work, I-Car Tests:

WKR01,FCR01,DAM01,DAM02,TRM01,STS01,EXT01,GLA01,WNW01,PLA01,PLA02,ADH01,WCS01,WCS04,EXT02,WCS02,WCS03,MEA01,SSS01,CPS01,FOM01,SPS01,SPS02,SPS03.SPS04,SPS05,SPS06,REF04,REF01,REF02,REF03,DAM03,PWR01

Outcome: Collision-damaged - Diagnose and repair collision-damaged mechanical and electrical components

Benchmark: 90%

Results			
Result	Action	Follow-Up	Action Status
05/23/2014 - 4 of 4 students completed with a 90% or above. benchmark meet at 100%			No Action Required
Result Type: Benchmark Met			

Live work, I-Car Tests:

WKR01,FCR01,DAM01,DAM02,TRM01,STS01,EXT01,GLA01,WNW01,PLA01,PLA02,ADH01,WCS01,WCS04,EXT02,WCS02,WCS03,MEA01,SSS01,CPS01,FOM01,SPS01,SPS02,SPS03.SPS04,SPS05,SPS06,REF04,REF01,REF02,REF03,DAM03,PWR01

Outcome: Painting and refinishing - Demonstrate automobile painting and refinishing skills

Benchmark: 90%

Results			
Result	Action	Follow-Up	Action Status
05/23/2014 - 76% 16 of 21 passed with a 85% or above Result Type: Benchmark Not Met			Action Plan in Progress

Live work, I-Car Tests:

WKR01,FCR01,DAM01,DAM02,TRM01,STS01,EXT01,GLA01,WNW01,PLA01,PLA02,ADH01,WCS01,WCS04,EXT02,WCS02,WCS03,MEA01,SSS01,CPS01,FOM01,SPS01,SPS02,SPS03.SPS04,SPS05,SPS06,REF04,REF01,REF02,REF03,DAM03,PWR01

Outcome: Safe working habits - Demonstrate safe working habits and procedures within an auto collision/repair facility

Benchmark: 90%

Results			
Result	Action	Follow-Up	Action Status
05/23/2014 - 21 of 21 passed the safety test before entering the shop Result Type: Benchmark Met			No Action Required

Indirect

No Assessment Tools reported for this Assessment Method Category

No Assessment Method Category specified.

No Assessment Tools reported for this Assessment Method Category